

CORNER RECORD

COUNTY OF INYO MOND T. 9 N R. 22 E MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER ☒ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐
 CORNER IDENTIFICATION - DATE OF VISIT 21 AUG 1975

26 0 25
 35 36

Observed and photographed by M. Allstead

$\frac{1}{4}$ Corner

CORNER - LEFT AS FOUND ☒ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Roll #2 Frame #5 - Close up of GLO cap and $\frac{1}{2}$ " pipe with lettering facing NW

Roll #2 Frame #6 - From 20± ft above and behind the corner, looking toward the Northeast to the gravel pit, Hwy 395 and a 45 MPH sign on left side of Hwy.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

POINT IS US GLO SURVEY CAP MOUNTED ON 1" PIPE 1.0'± ABOVE GROUND. STATION IS LOCATED WEST OF RTE. 395 AND 200± YDS. SOUTH OF GRAVEL PIT. IT CAN BE REACHED BY DRIVING ON DIRT ROAD AT GRAVEL PIT.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐

STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

← N →



$\frac{1}{4}$ corner, $\frac{1}{2}$ " diam steel pipe, lath, and rocks

2 wheel drive dirt road

from the gravel pit 25± ft. West of corner

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 8-21-75 7-28 1978

SIGNED: Kevin C. J. [Signature]

L.S. or P.C.E. No. 4468

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. 91122-25-2

STATEMENT ON BACK OF SHEET

YES ☐ NO ☐